

Cable Management Bar Mounting Brackets

The following installation instructions are intended to be used when installing the following Signamax connecting hardware:

CMB-B1-B

CMB-B12-B

and all kits that include them.


NOTES:

1. Patch panels shown in these instructions used for example purposes only; actual product may be any unit of passive or active equipment compatible with CEA-310-D 19-in mounting specifications.
2. Brackets may be installed independently, directly on a flange.


- 1** Loosen two mounting screws on one side of the equipment unit. Leave approximately 2 mm (1/8 in) under the screw head **1**.



- 2** Orient one of the brackets according to the sign on its rear surface **1** and slide under the screws **2**.



- 3** Tighten the screws **1**.



- 4** Loosen two mounting screws on the opposite side of the equipment unit. Leave approximately 2 mm (1/8 in) under the screw head **1**.



- 5** Slide the second bracket under the screws **1**. Position the bracket as needed **2**.



- 6** Tighten the screws **1**.

